

Incident Report: Valve V-301 Leakage

Incident ID: INC-2025-889. Date: 2025-06-18. Plant Area: Unit 3 Distillation.

Description: Steam leakage was observed from control valve V-301 flange gasket.

Root Cause Analysis (RCA): The gasket degradation was due to deferred maintenance. Flange bolts were loose and showed corrosion.

Corrective Actions: Flange gasket replaced with high-temperature graphite gasket. Flange bolts retorqued.