

Safety Procedures — Aurora Petrochemical Refinery

Pasadena, TX · Document ID: APR-SAF-001 · Revision 3 · Effective 01 Feb 2026

Document ID	APR-SAF-001	Revision	3
Plant	Aurora Petrochemical Refinery	Effective Date	01 Feb 2026
Document Owner	HSE Director: M. Castaneda	Classification	Controlled — Site Use

1. Purpose & Scope

This document defines safety procedures for Aurora Petrochemical Refinery (APR), Pasadena, TX. It applies to all employees, contractors, and visitors entering Operating Units 200 (Crude/Vacuum), 300 (Hydrotreater), and 400 (Reformer). Applicable regulatory frameworks include OSHA Process Safety Management 29 CFR 1910.119 and EPA Risk Management Program 40 CFR 68.

2. Regulatory & Standards Basis

Applicable: OSHA 29 CFR 1910.119, EPA RMP.

3. Site Hazard Inventory

The principal site hazards at Aurora Petrochemical Refinery (Pasadena, TX) include: flammable hydrocarbons, H2S, high-pressure steam. The full hazard inventory is summarized below; refer to the linked SOPs for detailed controls.

ID	Hazard	Primary Control
H-01	Flammable hydrocarbons	Class I, Div 1 electrical area; ignition sources prohibited.
H-02	Hydrogen sulfide (H2S)	Personal monitors required; 10 ppm action level, 100 ppm IDLH.
H-03	High-pressure steam (600 psig)	Hot work permit and steam isolation per LOTO-APR-014.
H-04	Pyrophoric iron sulfide	Wet-down protocol during vessel entry; refer to PRO-APR-031.
H-05	Confined space (vessels, sumps)	Permit-required entry per OSHA 1910.146; attendant mandatory.

4. Procedures

4.1 Hot Work

Hot work permits issued by Operations Shift Supervisor only after gas test by qualified Fire Watch. Re-test at minimum every 2 hours and after any process upset. Reference: PRO-APR-022 Rev 6.

4.2 Lockout/Tagout (LOTO)

Energy isolation follows the group lockout method documented in LOTO-APR-014. Each authorized employee applies a personal lock to the lockbox. Try-out of equipment is mandatory before maintenance begins.

4.3 Confined Space Entry

Two independent atmospheric tests (O2, LEL, H2S, CO) at minimum at top, middle, bottom of space. Continuous monitoring is required. Rescue services on-site for IDLH entries.

4.4 Emergency Response

Plant-wide alarm: long tone = shelter-in-place, intermittent = evacuate to muster point per WIND ROSE. Muster points published on Drawing APR-EMG-001. Headcount within 15 minutes.

5. Roles & Responsibilities

The HSE Director owns this procedure. Line Supervisors are accountable for daily compliance. Employees and contractors are responsible for stopping work in the event of an unsafe condition (Stop Work Authority).

6. References

- OSHA 29 CFR 1910.119 — Process Safety Management
- EPA 40 CFR 68 — Risk Management Program
- Internal: PRO-APR-022 Hot Work, LOTO-APR-014, PRO-APR-031 Pyrophoric Handling
- API RP 2001 — Fire Protection in Refineries

7. Revision History

Rev	Date	Author	Summary
1	12 Mar 2024	M. Castaneda	Initial issue.
2	08 Aug 2025	M. Castaneda	Added confined-space monitoring requirements.
3	01 Feb 2026	M. Castaneda	Annual review; aligned with updated regulator guidance.

Approvals

Role	Name	Signature	Date
HSE Director	M. Castaneda	_____	01 Feb 2026
Quality Assurance	K. Iyer, QA Manager	_____	01 Feb 2026
Operations / Site Lead	T. Whitfield, Operations Director	_____	01 Feb 2026

CONFIDENTIAL — Controlled Document. Uncontrolled when printed. Reproduction outside the parent organization requires written authorization.