VISIONGUARD QA - AUTOMATED QUALITY INTELLIGENCE

Audit Ref: VG-8D-000787

FORMAL 8D DISCREPANCY & ROOT-CAUSE AUDIT REPORT

Date: N/A

PRIMARY DEFECT:	SEVERITY RISK:	STANDARD:
CRAZING	CRITICAL	ISO 9001:2015

D1 - CROSS-FUNCTIONAL TEAM ESTABLISHMENT

Team Champion: Quality Assurance Director / Plant Manager

Core Team Members: Lead Process Metallurgist, Mill Superintendent, QA Reliability Specialist

D2 - PROBLEM DESCRIPTION & PHYSICAL SCOPE

Failure Mechanism: Surface morphological anomaly

Tooling Station: Main Rolling Finishing Mill Stand F2

Problem Detail: Optical anomaly detected on specimen VG-8D-000787 exceeding surface texture threshold.

D3 - INTERIM CONTAINMENT ACTIONS (ICA)

Immediate Containment: Quarantine affected manufacturing lot immediately.

D4 - ROOT CAUSE ANALYSIS (RCA / 5-WHY)

Root Cause Mechanism: Test root cause

D5 - PERMANENT CORRECTIVE ACTION (PCA)

Selected PCA: Inspect and redress work rolls; adjust coolant nozzle spray angles.

D6 - IMPLEMENTATION & VALIDATION

Execution Verification: Tooling replacement scheduled and optical inspection verified on next 10 consecutive batches.

D7 - PREVENT RECURRENCE & STANDARDIZATION

Systemic Prevention: Update Process FMEA (PFMEA-VG-084) and recalibrate maintenance intervals.

D8 - CONGRATULATE TEAM & SIGN-OFF

Closure Status: 8D Discrepancy report validated and approved for production resumption.