


		CEINSYS TECH LTD., 10/5, IT Park, Nagpur 440022 EHS LINE WALKTHROUGH			Doc no:- IMS/EHS/FR/ELW Version:- 1.0 Issue Date:- 16.09.2025	
Location : - Ceinsys Tech Ltd ,Head office						
Name of Contractor : - NA						
Members Present During visit :- Anil Selkari(EHS Head -CS TECH Ai), Smita Ragenwar(Quality Head -CS TECH Ai) Date :- 02.04.2026						
Observe Work Practices:						
Sr.No	Observation	Severity(High/Medium/Lo	Evidence(Photos)	Responsibility	Target Date	Suggested Corrective/Preventive
1	Emergency exit route blocked due to storage of AC compressors on exit route.	HIGH		Admin dept	Immediate Basis	Emergency exit routes to be kept clear all time.
2	First aid contents missing at first aid box located at cafeteria not maintained as per content list.	HIGH		Admin dept	Immediate Basis	First aid box to be maintained as per content list provided and handover to Canteen staff to avoid theft of first aid content at cafeteria.
3	No watertank cleaning tracking sheet displayed and maintained.	HIGH		Admin dept	Immediate Basis	Watertank cleaning checklist is to be displayed and maintained for all water coolers
4	Poor material storage at Kitchen storage room.Chances of fall of material and on person and cause serious injuries.	HIGH		Admin dept	Immediate Basis	Material to be stacked properly avoiding overstacking to prevent fall of material.
5	It was observed that some file storage racks are tilted to one side, creating a risk of toppling. This condition may lead to the collapse of nearby racks, posing a potential safety hazard to personnel and property.	HIGH		Admin dept	Immediate Basis	All tilted storage racks should be identified and properly realigned to ensure correct stacking. The racks must be securely fixed, preferably with adequate support from walls, to prevent instability and the risk of toppling.