## Scientific Scientific

System Fault Warning N/R N/R N/R

ZOOM ® View<sup>TM</sup>

Tachy Mode

Device

Date of Birth

INCEPTA ICD F160/101210 Implant Date Last Office Interrogation 07 Jun 2017

Report Created 24 Apr 2018

## Warning Details

Capacitor charge time has exceeded the limit. Contact Technical Services with code 1007.

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

F160 Firmware 2868 Software Version: 4.04

Version: B\_v1.02.00(4.01)

or its affiliates. All rights reserved. **Boston Scientific Corporation** Page 1 of 1 © 2016

Clinician Signature: