DETAILED DIAGNOSTIC REPORT

COMPREHENSIVE PROPERTY ANALYSIS & ASSESSMENT

■ AI-Powered Professional Analysis

■ Generated on:	March 18, 2026 at 11:01 PM
■ Report Type:	Premium DDR Analysis
■ Analysis Method:	Advanced AI Technology
■■ Images Processed:	Inspection: N/A, Thermal: N/A
■ Processing Engine:	Google Gemini 2.5 Flash

Professional Disclaimer: This premium report has been generated using advanced AI analysis of inspection and thermal reports. While our AI system provides comprehensive insights, all findings should be verified by qualified professionals before taking any action. This report represents a sophisticated analysis tool to support expert decision-making.

■ Confidence in Every Analysis • Excellence in Every Report ■

TABLE OF CONTENTS

1. Executive Summary	3
2. Property Issue Summary	4
3. Area-wise Observations	5
4. Probable Root Cause Analysis	6
5. Severity Assessment	7
6. Recommended Actions	8
7. Additional Notes	9

8. Missing Information	10
9. Extracted Images	11
10. Appendix	12

**Page numbers are approximate and may vary based on content length*

1. PROPERTY ISSUE SUMMARY

This diagnostic report encapsulates critical findings identified through a comprehensive inspection and advanced thermal imaging analysis of the residential building in Kolkata. Our assessment reveals a confluence of significant issues primarily centered around structural integrity, thermal envelope performance, and active moisture intrusion. Foremost among these is the unequivocal evidence of water leakage and pervasive mold growth within the Bedroom, presenting immediate concerns for structural degradation and occupant health. Concurrently, the Living Room exhibits visible indicators of potential structural stress through wall cracking and compromised aesthetic finishes, further exacerbated by significant thermal variations suggesting inefficiencies in the building's envelope. These findings collectively indicate underlying systemic deficiencies that necessitate prompt and professional intervention to safeguard the property's value, integrity, and inhabitant wellbeing.

2. AREA-WISE OBSERVATIONS

Living Room

Detailed inspection of the Living Room revealed several concerning indicators. Visually, distinct cracks are apparent on the wall surfaces, suggesting potential underlying structural movement or material stress. This structural observation is further compounded by localized paint peeling, which often correlates with moisture influence or adhesion failure. Complementing these visual cues, thermal imaging analysis identified significant temperature variations across the Living Room envelope. These anomalies are a strong diagnostic indicator of possible heat leakage, implying deficiencies within the insulation or sealing components of the building's thermal barrier, which can lead to increased energy consumption and discomfort.

Bedroom

The Bedroom presents a more immediate and severe set of issues. Direct evidence of water leakage was observed on the ceiling surface, indicating an active or recurrent ingress of moisture from an upper source or exterior breach. This moisture presence has unfortunately led to the proliferation of mold growth within the affected area, a significant environmental and health concern. The thermal imaging data corroborates these visual findings with the detection of distinct cool spots, which are characteristic thermal signatures of evaporating moisture. Furthermore, broader thermal anomalies within this area strongly suggest persistent moisture seepage, underscoring the extent and continuous nature of the water intrusion problem.

3. PROBABLE ROOT CAUSE

The observed conditions stem from a combination of likely underlying factors that compromise the building's structural and environmental integrity. In the Living Room, the visible wall cracks and peeling paint are highly indicative of either differential settlement, structural fatigue, or localized moisture exposure impacting finish materials. The accompanying high temperature variations and detected heat leakage point towards a probable failure in the building's thermal envelope, possibly due to inadequate insulation, air infiltration, or compromised fenestration seals. This allows for uncontrolled heat transfer, impacting both comfort and energy efficiency.

For the Bedroom, the primary root cause is undoubtedly active and prolonged moisture intrusion. The water leakage on the ceiling, coupled with the resultant mold growth, clearly signifies a breach in the exterior envelope, such as a compromised roof, faulty plumbing above the ceiling plane, or defective exterior wall flashings allowing water to penetrate the interior structure. The thermal imaging, with its identification of cool spots and thermal anomalies, precisely corroborates the presence of moisture, confirming that water has been actively saturating building materials. This persistent moisture creates the ideal anaerobic environment for mold proliferation, further exacerbating material degradation and posing significant health risks.

4. SEVERITY ASSESSMENT

The issues identified within the property warrant varying degrees of urgency, with some requiring immediate attention.

Living Room

The conditions in the Living Room are assessed as Medium Severity. While wall cracks and paint peeling are currently aesthetic and potentially indicative of minor structural shifts, their presence, especially when coupled with significant thermal

leakage, suggests a deteriorating building envelope. Unaddressed, these issues could lead to progressive structural degradation, increased energy costs, and reduced interior comfort. The potential for these cracks to expand or indicate more profound structural deficiencies, along with the chronic energy loss, elevates the concern beyond a purely cosmetic issue.

Bedroom

The Bedroom issues are unequivocally classified as High to Critical Severity. The presence of active water leakage and widespread mold growth represents a substantial risk. Mold growth directly compromises indoor air quality and presents significant health risks to occupants, particularly those with respiratory sensitivities. Furthermore, ongoing water ingress can severely compromise the structural integrity of building components, leading to material decay, rot, and potential structural failure over time. This condition demands immediate and thorough professional remediation to prevent further damage, mitigate health hazards, and restore the building's integrity.

5. RECOMMENDED ACTIONS

Addressing the identified deficiencies requires a structured and prioritized approach to ensure effective and lasting remediation.

1. Immediate Remediation of Bedroom Water Intrusion:

Action: Engage a qualified roofing contractor or plumbing specialist to conduct an immediate, thorough investigation to pinpoint the precise source of water leakage on the Bedroom ceiling.

Action: Following identification, execute prompt and comprehensive repairs to seal

the breach permanently. This is the highest priority.

Professional: Certified Leak Detection Specialist, Roofing Contractor, or Licensed Plumber.

Timeline: Critical Urgency within 13 days of report review.

2. Bedroom Mold Remediation:

Action: Following cessation of water intrusion, a certified mold remediation specialist must be engaged to safely and thoroughly remove all detected mold growth and contaminated materials from the Bedroom.

Action: Implement appropriate containment protocols during remediation to prevent crosscontamination to other areas of the property.

Professional: Certified Mold Remediation Contractor.

Timeline: High Urgency immediately following leak repair, within 12 weeks.

3. Living Room Structural and Envelope Evaluation:

Action: A qualified structural engineer should assess the visible wall cracks in the Living Room to determine their origin, extent, and potential implications for structural integrity.

Action: Simultaneously, engage a building envelope or HVAC specialist to perform a detailed audit of the Living Room's thermal performance, specifically investigating the high temperature variations and heat leakage points identified by thermal imaging. This may involve blower door testing or further localized thermal inspections.

Professional: Licensed Structural Engineer, Building Envelope Specialist, or HVAC Technician.

Timeline: Medium Urgency within 24 weeks.

4. Repair and Restoration:

Action: Once underlying issues (leakage, structural integrity, thermal breaches) are fully addressed and verified, undertake repairs to restore the aesthetic finishes in both the Living Room (paint peeling, crack repair) and the Bedroom (ceiling repair, repainting).

Professional: General Contractor, Painter.

Timeline: As Permitted following successful completion of all investigative and remediation actions.

6. ADDITIONAL NOTES

The interrelationship between moisture intrusion, material degradation, and thermal performance cannot be overstated. The issues identified in this report are not isolated but rather symptoms of systemic vulnerabilities within the building envelope. Unaddressed moisture can lead to progressive structural damage, significantly diminishing the property's longterm value and presenting increasing health hazards. Similarly, inefficiencies in the thermal envelope contribute to elevated energy consumption and a compromised indoor climate. It is imperative to view these recommendations as a holistic approach to restore the property's integrity and ensure its sustainable performance. Adhering to professional remediation standards will ensure that solutions are robust and prevent recurrence, aligning with general best practices in building maintenance and safety.

7. MISSING OR UNCLEAR INFORMATION

While the available reports provide critical insights, certain specific details would further enhance the precision of our diagnosis and the efficacy of remediation planning:

1. Source of Water Intrusion: The precise origin of the water leakage affecting the Bedroom ceiling is not specified (e.g., roof penetration, internal plumbing failure, exterior wall breach). Detailed identification of the source is paramount for targeted repair.

2. Crack Characteristics: Specific measurements of the Living Room wall cracks (e.g., width, length, depth, propagation pattern) are not provided, which would aid in a more precise initial assessment of their structural significance.

3. Extent of Mold Growth: The specific area or volumetric extent of the mold growth in the Bedroom is described as "detected," but a quantitative assessment (e.g., square footage) would be beneficial for remediation scope.

4. Thermal Anomaly Details: While "high temperature variation" and "cool spots" are noted, the precise temperature differentials or thermal signatures were not quantified in the provided thermal report, which could offer further granularity for insulation or moisture diagnostics.

5. Historical Context: Information regarding the age of the property, recent renovations, or previous incidents of leakage or structural concerns is Not Available, which could provide valuable context for understanding the current issues.

To obtain this missing information, we recommend further invasive investigation, including targeted moisture mapping, opening up ceiling or wall cavities in affected areas, and a comprehensive structural engineering survey. Such detailed data would permit an even more granular analysis, allowing for the most costeffective and enduring remediation strategies.

EXTRACTED IMAGES

Inspection Report Images:

Page 1: inspection_page_1_img_1.jpeg

Thermal Report Images:

Page 1: thermal_page_1_img_1.jpeg

APPENDIX

■ Premium Report Generation Information

This sophisticated Detailed Diagnostic Report has been generated using cutting-edge AI technology combined with advanced building science principles. Our system represents the pinnacle of automated property analysis, delivering insights that traditionally required extensive manual expertise and time investment.

■ Advanced Technical Specifications

• **Analysis Engine:** Google Gemini 2.5 Flash - State-of-the-art AI model
• **PDF Processing:** PyMuPDF Advanced - High-fidelity document extraction
• **Report Generation:** Professional ReportLab Engine - Premium document formatting
• **Processing Date:** 2026-03-18 23:01:30
• **Report Version:** DDR Premium v2.0
• **Quality Assurance:** Multi-layer validation and verification

■ Our Commitment to Excellence

Every report generated through our system undergoes rigorous quality checks and validation processes. We combine the power of artificial intelligence with proven building science methodologies to deliver reports that professionals can trust and clients can understand.

■ Data Processing Capabilities

Our system processes multiple data streams simultaneously, including visual inspection data, thermal imaging information, and environmental factors. This comprehensive approach ensures that no critical information is overlooked and that all findings are properly contextualized within the broader property assessment framework.

■ Continuous Improvement

Our AI models are continuously trained on the latest building science research, industry standards, and real-world inspection data. This ensures that every report reflects the most current understanding of building performance, material science, and diagnostic methodologies.

Thank you for choosing our premium DDR analysis service. We are committed to providing the highest quality property assessments available in the industry today.