

### DEFECTS AND SCRATCH

→ Project Report Presentation ←

Name:- Pritam Nagar

**Department :-** Production (Intern)

**Institute**:- MANIT Bhopal

Branch & Degree :- Mechanical & B.Tech

(2<sup>nd</sup> year)

## EICHER TRACTOR MODEL 380







#### **« Model Description »**

Model Number: 380Brand Name: EicherPower Range: 29.42Kw

• HP Range : 40 hp


• Number of Speeds : 8 Forward & 2 Reverse

• Forward Speed : 38.84 Kmph

Total Weight: 1930 kgFuel Tank Capacity: 45 L



## DEFECTS OCCURRING DURING OBSERVATION




## MOSTLY OCCUR DEFECTS


- Hand Accelerator Rubber Out (ES 3)
- Battery Box Fitment Issues Such As Battery Clamp Bands, Mounting Issue
- At Some Stations QP And TOE Not Done Issue Occuring During Observation
- Recovery Tools And Proper Greasing Not Done
- Fuel Tanks, Mud Guard, Bonnet, Fuel Tank cover, Bonnet Paint Issue
- Mostly Observed Issue Fuel Tank & Fuel Tank Cover Scratched (Minor And Major)
- Sticker Alignment, TT Kit Foul And, Bonnet Lock Issues

## **SCRATCH REPORT DATA**

Scratch Type	Count of Model Number	
Bonnet LH	7	
Bonnet RH	8	
Boonet LH	1	
Bumper	1	
Fuel Tank LH	5	
Fuel Tank RH	15	
MudGuard RH	18	





	Count of	
Model Number	Scratch	
242	6	
330	3	
333	9	
368	1	
380	11	
480	1	
485	8	
551	11	
557	5	




## SCRATCH REPORT DATA


Vehical Type	Count of Scratch
ES 3	
333	2
380	5
551	2
Normal	
242	6
330	3
333	7
368	1
380	6
480	1
485	8
551	9
557	5








# SCRATCH REPORT Scratch Detailed Data Collection DATA



Count Of Scratch

Scratch As Per Model

Model Number	Count of Scratch Position	
242		
Bonnet LH		2
Fuel Tank LH		1
Fuel Tank RH		2
MudGuard RH		1
330		
Bonnet LH		1
Fuel Tank RH		1
MudGuard RH		1
333		
Bonnet RH		2
Fuel Tank LH		1
Fuel Tank RH		5
MudGuard RH		1
368		
MudGuard RH		1
380		
Bonnet LH		1
Bonnet RH		1
Fuel Tank LH		1
Fuel Tank RH		2
MudGuard RH		6
480		
Fuel Tank RH		1
485		
Bonnet LH		1
Bonnet RH		2
Fuel Tank LH		2
Fuel Tank RH		1
MudGuard RH		2
551		
Bonnet LH		1
Bonnet RH		2
Boonet LH		1
Bumper		1
Fuel Tank RH		2
MudGuard RH		4
557		
Bonnet LH		1
Bonnet RH		1
Fuel Tank RH		1
MudGuard RH		2



r OsiliOli	Colollill rapels																					
	24	2 242 Total	330	330 Total	333		333 Total	368	368 Total	380		380 Total	480	480 Total	485	485 Total	551		551 Total	557	557 Total	Grand Total
Row Labels	Normal		Normal		ES 3	Normal		Normal		ES 3	Normal		Normal		Normal		ES 3	Normal		Normal		
Bonnet LH		2 2	. 1	1							1	1			1	1		1	1	1	1	1 7
Bonnet RH						2	2				1	1			2	. 2		2	2	1	1	1 8
Boonet LH																		1	1			1
Bumper																		1	1			1
Fuel Tank LH		1 1			1		1				1	1			2	2						5
Fuel Tank RH		2 2	1	1	1	4	5			2		2	1	1	1	1		2	2	1	1	1 15


## SCRATCH POSITION REPORT DATA

### ES 3 V/s Regular Vehicles

- → ES 3 Vehicles ←
- > MudGuard Scratched (6)
- > Fuel Tank Scratch LH(1)
- ➤ Fuel Tank Scratch RH(3)

- → Regular Vehicles ←
  - > Fuel Tank Scratch (16)
  - ➤ MudGuard Scratch (12)
  - **→ Bonnet Scratch (16)**

## REASON'S OF SCRATCHES







### Fuel Tank Scratch

- Mishandling During Assembly
- > Improper Handling Equipment
- ➤ Rough Handling By Workers
- Kitting Trolleys Sharp Locking Knob

### Mud Guard Scratch

- Forcely Pulling By Worker To Save Time
- > Transportation and Fitting Time
- Loading And Unloading Time
- ➤ Worker Wearing Unusual Accessories

### » Bonnet Scratch

- Loading Unloading Time irresponsibility From Workers
- Ignoring Minor Scratches
- Fitting Time

## **SCRATCH'S IMAGES**













## **MUD GUARD IMAGES**



## **BONNET SECTION SCRATCH**

### **Action Performed To Reduce**

#### : tmproved Handling Procedures :-

► Implementing Careful Handling Procedures During Assembly To Minimize The Risk Of Scratches During Transportation and Installation.

#### **Protective Coverings:-**

 Utilizing Temporary Protective Coverings Or Coating On Fuel Tanks During Assembly And Transportation To Shield Them.

#### **Protective Kitting Trollies:-**

 Provide Rubber Or Tapping On The Edges Of Kitting Trollies To Reduce The Scratch From Their Sharp Edges Or Knob.



## **FUEL TANK SCRATCH ACTION**

#### **Action Performed To Reduce**

#### **Improved Handling Procedures:**

► Implementing Careful Handling Procedures During Assembly To Minimize The Risk Of Scratches During Transportation and Installation.

#### **Protective Coverings:-**

 Utilizing Temporary Protective Coverings Or Coating On Fuel Tanks During Assembly And Transportation To Shield Them.

#### <u>Pre-Assembly & Post-Assembly</u> <u>Inspection :-</u>

▶ Inspect The Fuel Tank Before And After The Installation To Ensure That The Are Scratch Free And Undamaged.



## FUEL TANK SCRATCH ACTION



Theme	Scratch improvement	TMTL Bhopal :-May-24 Date- 29-05-24				
	Before	After				
Photo (s)						
Problem / Cause & Solution	Problem statement: Fuel Tank Scratches Cause: Due To Sharp Knob And Edges Identified Solution: Trolley need to be modify	Solution Deployed: Provide Rubber Grips And Tapping On Edges And Knobs Of Trolley				
Benefit	Fuel Tank Are In Scratched Condition, Rework ppm reduced	Scratch Chances Reduces Provide More Protection To Fuel Tank During Transportation				
Savings	NIL	NIL				



## **CHECK SHEET**

Serial No.	Station	Tackle	Action Taken				
01	Fuel Tank Cover	To Ensure No Metal To Metal Connection Occurred	Provide Rubber Grip and Tapping On Locking Hook				
02	Mud Guard Fitment	To Ensure No Metal To Metal Connection Occurred	Cut The Extra Thick Sharp Edges Of Trolley Also Used Rubber Pipe In Kitting Trolley				
03	Bonnet Fitment	To Ensure No Metal To Metal Connection Occurred	Provide Cotton Clothe And Tapping On Locking Hook				



## THANK

Y0U