



Vacuum-Pressure Oil Impregnation Process

1. HEAT
BEARINGS




80–90°C

2. APPLY
VACUUM




< 50 mbar

3. INTRODUCE
OIL




*Oil covers
bearings*

4. APPLY
PRESSURE



3–5 bar

5. DRAIN &
STABILIZE



*90–98% oil
fill achieved*