

Transmission Angle in Four-Bar Linkage


DESIGN GUIDELINES

Ideal: $\mu = 90$ deg

Good: $40 \text{ deg} < \mu < 140 \text{ deg}$

Minimum: $\mu > 30 \text{ deg}$

Avoid: μ near 0 deg or 180 deg



Why it matters:

Poor transmission angle causes high joint forces and jerky motion