Transmission Angle in Four−Bar Linkage

DESIGN GUIDELINES

Ideal: $\mu = 90$ deg

Good: 40 deg < μ < 140 deg

Minimum: $\mu > 30$ deg

Avoid: μ near 0 deg or 180 deg



Why it matters:
Poor transmission angle causes high joint forces and jerky motion