
Forming Limit Diagram (FLD)
FAILURE ZONE
SAFE ZONE
Forming Limit Curve (FLC)
Plane Strain
Drawing
Stretching
Major Strain (e1)
Minor Strain (e2)
70%
60%
50%
40%
30%
20%
10%
0%
−30%
−20%
−10%
0%
10%
20%
30%
40%