Basic Welding Symbol Structure

KEY RULE:

Symbol BELOW reference line = Arrow Side

Symbol ABOVE reference line = Other Side