



Common Weld Defects

POROSITY




Gas pockets
trapped in weld

UNDERCUT




Groove melted into
base metal at toe

LACK OF FUSION




Weld metal doesn't
fuse with base

INCOMPLETE PENETRATION




Root not
fused

CRACK



Most serious
defect

SPATTER



Metal droplets
on surface