



# Vacuum-Pressure Oil Impregnation Process

1. HEAT  
BEARINGS




*80–90°C*

2. APPLY  
VACUUM




*< 50 mbar*

3. INTRODUCE  
OIL




*Oil covers  
bearings*

4. APPLY  
PRESSURE



*3–5 bar*

5. DRAIN &  
STABILIZE



*90–98% oil  
fill achieved*