

# Two Mistakes That Waste Resources and Reduce Quality

Control charts help us avoid both mistakes

## MISTAKE #1

*Over-adjustment*

Treating COMMON cause  
as if it were SPECIAL

Result: Tampering  
Increased variation!

## MISTAKE #2

*Under-reaction*

Treating SPECIAL cause  
as if it were COMMON

Result: Missing signals  
Defects produced!