Two Mistakes That Waste Resources and Reduce Quality

Control charts help us avoid both mistakes

MISTAKE #1

Over−adjustment

Treating COMMON cause
as if it were SPECIAL

Result: Tampering
Increased variation!

MISTAKE #2

Under−reaction

Treating SPECIAL cause
as if it were COMMON

Result: Missing signals
Defects produced!