# Industrial Robot Configurations

Different types optimized for specific applications

## Articulated (6−axis)

Most versatile
Human−like motion
6 degrees of freedom

*Welding, painting assembly, handling*

## SCARA

Fast horizontal motion
Rigid vertical axis
4 axes typical

*Assembly, pick−place packaging*

## Delta (Parallel)

Very high speed
Limited payload
Parallel linkage

*High−speed picking packaging, assembly*

## Cartesian (Gantry)

Linear motion
Large work envelope
3−4 axes

*CNC loading, palletizing large part handling*

## Cylindrical

Rotary base
Linear reach
4 axes typical

*Machine tending material handling*

## Collaborative (Cobot)

Force limited
Safe around humans
Easy programming

*Human collaboration assembly assist*