
Optimal Standing Work Surface Heights by Task Type
Heights in cm from floor − adjust based on worker height
Height (cm)
120
110
100
90
80
70
60
Precision
100−110cm
Light Assembly
85−95cm
Heavy Work
70−85cm
Elbow
(stand
Precision
Light Assembly
Heavy Work
Task Type