
Impact of Measurement System Quality on Control Charts
Same stable process measured with different gauge quality (same y−axis scale on both charts)
Good MSA (%GRR = 15%)
Poor MSA (%GRR = 93%)
Measured Value
Sample Number
110
100
90
0
10
20
30
40
50