

# Fishbone Diagram: Parts Have Surface Scratches

Brainstorming potential causes organized by 6M categories

