
The P−F Curve
Different sensor types detect failure at different positions on the curve
Component condition (%)
100
80
60
40
20
0
P: First
detectable sign
Vibration
Temperature
Motor
current
Audible
noise
Visual
signs
F: Functional
failure
P−F Interval
(decision window)
0
25
50
75
100
Time (operating cycles or hours)