
X−bar Control Chart Example
Monitoring process mean with subgroups of n=5
Special cause!
Investigate
UCL = 50.4
CL = 50
LCL = 49.6
Subgroup Mean (mm)
51.0
50.5
50.0
49.5
0
5
10
15
20
25
30
Subgroup Number
In Control
Out of Control