

Manufacturing Process Selection Guide

Choose processes based on volume requirements and part complexity

Part Complexity

Very High

High

Medium

Low

Simple

Prototype
(1-10)

Low
(10-1K)

Medium
(1K-10K)

High
(10K-100K)

Mass
(100K+)

Production Volume

Category



Additive



Forming



Machining



Casting



Joining



Molding

3D Printing

Injection Casting

CNC Machining

Injection Molding

Manual Assembly

Sand Casting

Die Casting

Thermoforming

Blow Molding

Foaming

Stamping

Extrusion