

SOLIDWORKS > Home > Sketch > Line > Corner > Circle > Polygon > Centerpoint > Spline > Smart Dimension > Add Relation > Sketch Fillet Entities > Linear Sketch Pattern > Offset Entities > Convert Entities > Extruded Boss/Base > Extruded Cut > Fillet > Linear Pattern > Mirror > Draft > Shell > Reference Geometry > Measure > Mass Properties

Basic Modeling Tools SOLIDWORKS CAM SOLIDWORKS CAM TBM Simulation Analysis Preparation

Mass Properties

lab 3 part 2

Options... Override Mass Properties... Recalculate

Include hidden bodies/components

Create Center of Mass feature

Show weld bead mass

Report coordinate values relative to: -- default --

Mass properties of lab 3 part 2
Configuration: Default
Coordinate system: -- default --

Density = 0.04 pounds per cubic inch

Mass = 0.06 pounds

Volume = 1.57 cubic inches

Surface area = 14.56 square inches

Center of mass: (inches)
X = 0.00
Y = 2.61
Z = -0.75

Principal axes of inertia and principal moments of inertia: (pounds * square inches)
Taken at the center of mass.
Ix = (0.00, 0.97, -0.26) Px = 0.03
Iy = (0.00, 0.26, 0.97) Py = 0.10
Iz = (1.00, 0.00, 0.00) Pz = 0.13

Moments of inertia: (pounds * square inches)
Taken at the center of mass and aligned with the output coordinate system. (Using positive)
Lxx = 0.13 Lxy = 0.00 Lxz = 0.00
Lyx = 0.00 Lyy = 0.04 Lyz = -0.02
Lzx = 0.00 Lzy = -0.02 Lzz = 0.10

Moments of inertia: (pounds * square inches)
Taken at the output coordinate system. (Using positive tensor notation.)
lxz = 0.55 lxy = 0.00 lxz = 0.00
lyx = 0.00 lyx = 0.07 lyz = -0.13
lzx = 0.00 lzy = -0.13 lzz = 0.48

Help Print... Copy to Clipboard

3DEXPERIENCE Marketplace to source 3D content and services worldwide. (No license required.)

Let's get started

SOLIDWORKS > Home > Sketch > Line > Corner > Circle > Polygon > Centerpoint > Spline > Smart Dimension > Relation > Add Relation > Sketch Entities > Trim Entities > Linear Sketch Pattern > Offset Entities > Convert Entities > Mirror Entities > Extruded Boss/Base > Extruded Cut > Fillet > Linear Pattern > Mirror Draft Shell > Reference Geometry > Measure > Mass Properties

Basic Modeling Tools SOLIDWORKS CAM SOLIDWORKS CAM TBM Simulation Analysis Preparation

Mass Properties

lab 3 part 3

Override Mass Properties... Recalculate Options...

Include hidden bodies/components
 Create Center of Mass feature
 Show weld bead mass
Report coordinate values relative to: -- default --

Mass properties of lab 3 part 3
Configuration: Default
Coordinate system: -- default --


Density = 0.04 pounds per cubic inch
Mass = 0.14 pounds
Volume = 3.80 cubic inches
Surface area = 24.19 square inches
Center of mass: (inches)
X = 0.00
Y = 4.48
Z = 0.81

Principal axes of inertia and principal moments of inertia: (pounds * square inches)
Taken at the center of mass.
Ix = (0.00, 0.99, 0.15) Px = 0.06
ly = (0.00, -0.15, 0.99) Py = 0.86
lz = (1.00, 0.00, 0.00) Pz = 0.91

Moments of inertia: (pounds * square inches)
Taken at the center of mass and aligned with the output coordinate system. (Using positive tensor notation.)
Lxx = 0.91 Lxy = 0.00 Lxz = 0.00
Lyx = 0.00 Lyy = 0.08 Lyz = 0.12
Lzx = 0.00 Lzy = 0.12 Lzz = 0.84

Moments of inertia: (pounds * square inches)
Taken at the output coordinate system. (Using positive tensor notation.)
ixx = 3.75 ixy = 0.00 ixz = 0.00
lyx = 0.00 lyy = 0.17 lyz = 0.62
lzx = 0.00 lzy = 0.62 lzz = 3.59

Help Print... Copy to Clipboard



3DEXPERIENCE Marketplace

Extend SOLIDWORKS with the 3DEXPERIENCE Platform

Connect to the 3DEXPERIENCE platform and leverage its collaboration, product data and lifecycle management, organic shape design, simulation solutions, and more. (Subscription required.)

Use 3DEXPERIENCE Marketplace to source 3D content and services worldwide. (No license required.)

Let's get started

SOLIDWORKS Student Edition - Academic Use Only

Simplified Interface IPS