

MAINTENANCE INSPECTION REPORT

Facility: Riverside Processing Plant - Unit 3
Report Date: 2026-06-30 Prepared By: OpsBrain QA Team

1. SUMMARY

Routine inspection of eighteen assets across the pump, valve, compressor, heat exchanger, tank, boiler, and fan systems was completed between January and May 2026. Six assets required corrective action, most commonly related to seal or gasket wear, vibration exceeding threshold, or minor corrosion at flanged connections. All corrective actions were completed on the same visit with the exception of PMP-601, where a replacement temperature sensor was back-ordered for two weeks. No critical safety findings were identified during this inspection cycle.

2. INSPECTION FINDINGS

Equipment ID	Inspection Date	Technician	Issue Found	Action Taken	Next Due Date
P-101	2026-01-10	R. Mehta	Minor corrosion noted	Cleaned and repainted	2026-07-10
P-102	2026-01-12	S. Iyer	Vibration above threshold	Rebalanced rotor	2026-04-12
V-204	2026-01-18	A. Khan	Seal leak detected	Replaced seal	2026-04-18
V-205	2026-01-22	J. Fernandes	No issues found	None required	2026-07-22
C-301	2026-02-02	P. Rao	Bearing wear observed	Bearing replaced	2026-05-02
C-302	2026-02-05	N. Sharma	Pressure gauge faulty	Gauge recalibrated	2026-05-05
HX-401	2026-02-14	R. Mehta	Insulation damage	Insulation repaired	2026-05-14
HX-402	2026-02-20	S. Iyer	Corrosion at flange	Flange repaired, repainted	2026-05-20
T-501	2026-03-01	A. Khan	Abnormal noise	Bolts tightened	2026-06-01
T-502	2026-03-06	J. Fernandes	Leak at valve stem	Packing replaced	2026-06-06
PMP-601	2026-03-15	P. Rao	Temperature sensor drift	Sensor replaced	2026-06-15
PMP-602	2026-03-19	N. Sharma	Coupling misalignment	Coupling realigned	2026-06-19
CV-701	2026-04-02	R. Mehta	No issues found	None required	2026-10-02

2. INSPECTION FINDINGS (continued)

Equipment ID	Inspection Date	Technician	Issue Found	Action Taken	Next Due Date
CV-702	2026-04-09	S. Iyer	Oil contamination	Oil changed, filter replaced	2026-07-09
BLR-801	2026-04-16	A. Khan	Gasket deterioration	Gasket replaced	2026-07-16
BLR-802	2026-04-23	J. Fernandes	Fan blade imbalance	Blade cleaned, rebalanced	2026-07-23
FN-901	2026-05-04	P. Rao	Control valve sticking	Valve serviced	2026-08-04
FN-902	2026-05-11	N. Sharma	No issues found	None required	2026-11-11

3. RECOMMENDATIONS

Continue current preventive maintenance intervals for all pump and valve assets. Increase vibration monitoring frequency on P-102 given repeat findings in the prior two inspection cycles. Prioritize replacement of the PMP-601 temperature sensor once the back-ordered part arrives, and flag CV-702 for an oil analysis at the next scheduled visit to confirm contamination has not recurred. No changes to inspection scope are recommended at this time.