QATCH Technologies Release Notes

	Software v2.6r64	Firmware v2.6r64
	Updated build info Release date 10/13/2025	Updated build info Release date 10/13/2025
Features & Enhancements Added	 Updated build information and resources to v36 Upgraded to QModel v4 (Fusion) with PyTorch backend Merge issue #203: Switch from TensorFlow to PyTorch. Merge issue #84: NEW: VisQ.Al. Merge issue #206: Interpolated viscosity reporting. Merge issue #193: License server integration and bugfixes Merge issue #184: Improve analyze footnote formatting. Merge issue #177: Add temperature handling to table. Merge issue #175: Rename "Predict" to "Auto-Fit" Merge issue #171: Remove live fill forecasting. Merge issue #168: Add missing icon for run info window. Merge issue #160: Delete image clustering module Merge issue #158: Protections against pruning base model Merge issue #147: Hide POI3 from UI. Add device fingerprinting for license management Implement constraint-based sampler and optimizer Add batch processing mode for loading multiple runs Enhance protein handling with new ProteinClass enum Add progress dialog for model prediction feedback Improve error handling and logging across modules Add viscosity average and standard deviation to analysis. Refactor ingredient selection logic and fuzzy matching Update constraints for protein concentration limits Add nightly update checks with resource validation 	- Merge issue #94: Fan stays on after cooldown ends - Align fan off event with displayed countdown timer - Temp Control heat limit increased from 200 to 255

Release Notes

Bugs Fixed	 Merge issue #211: Fix frozen app path resolution. Merge issue #207: Fix drop effect. Merge issue #204: Fix SQLite closed database errors. Merge issue #201: Optimize fill region analysis. Merge issue #197: Buffer concentration validation. Merge issue #196: Fix protein class field not persisting. Merge issue #186: Enhance serial and elaborate process Merge issue #180: Fix hourly background license refresh Merge issue #179: Fix protein class field stuck as none Merge issue #178: Fix temp control out-of-sync error. Merge issue #170: Hot fix for time index calculations. Merge issue #167: Fix Ch1 point window size too narrow Merge issue #166: Fix plot data out of sync during redraw BUG FIX: "No serial response from device" error seen on measurement startup due to race condition at serial buffer stream start code in SW 	- NONE
Known Issues	 Issue #227: Initialization temp check fails during tec cooldown. Issue #77 Export Functionality with preferences support Issue #47: Missing plate-config.json breaks ability to run device SW. Issue #45: Rename run on initial run info screen does not occur. Issue #21: FW update hangs on 'Failed to reboot' ERROR message. 	- NONE