

SOP-HSE-040 H2S Exposure Response

Revision B - Owner: Technical Services - Classification: Internal

1. Alarm levels

Personal H2S monitors alarm at 5 ppm (low) and 10 ppm (high). Fixed area detectors alarm at 10 ppm and 20 ppm.

2. Immediate actions

On a high alarm, stop work, move upwind or crosswind to the muster point and report to the control room. Do not re-enter until the area authority confirms H2S below 1 ppm.

3. Rescue

Rescue of a casualty requires breathing apparatus. Never attempt rescue without it.