

INSPECTION REPORT IR-2026-0151

Equipment: V-3102 Hydrotreater high-pressure separator

Unit: Diesel Hydrotreater 3

Inspection date: 28-Aug-2026 **Previous inspection:** 30-Aug-2021

Inspector: S. Menon (synthetic)

Thickness readings (UT), interval 5.0 years

CML	Location	t prev (mm)	t actual (mm)	t min (mm)	CR (mm/yr)	RL (yr)
C1	Shell course 1	38.0	37.6	31.0	0.080	82.5
C2	Shell course 2	38.0	37.7	31.0	0.060	111.7
C3	Bottom head	40.0	39.1	32.5	0.180	36.7

Findings

1. Wall loss is uniform and low. Minor coating breakdown on the external insulation support ring.

Recommendation

Continue the 5-year internal inspection interval. Repair external coating at the next opportunity.