		1	purarion
	Activity	Predecessor	B-0-1
Α.	gather Requirements & Stakeholds Identification		10
В.	Find Best Quality Sensors, Durable Helmets & check their Integrity.	Α	16
<i>C</i> .	connect all the Required 107 sensors in the Helmet & Fix it at place	В	20
D .	White code for Internet (WiFi) connection that indicates emuginally whenever required to all at site & the sensors	В	10
E.	check the working of Helmed integrated sonvers & signal Recieving.	CID	10
₹.	Test the accusacy of Working	E	16
G1.	Deliver the Product & Recieve Feedback	F	5

