
ME251 Engineering Design and Graphics-Laboratory exercise 1

Friday, July 29, 2016

Draw the top view, front view (shown by arrow) and profile view (looking from right) of the machine part given in the figure below in third angle projection. Indicate the dimensions in the respective views. DO NOT duplicate dimensions in different views. Show hidden lines and center lines in all views using the appropriate line type. Draw in full scale (1:1).



All dimensions in mm