RESPIRONICS

Alvin Drive New Kensington PA 15068US

NYX NEW ALBANY
FED EX GROUND
999 PROGRESS BOULEVARD
NEW ALBANY IN 47151
UNITED STATES OF AMERICA

RETURN to VENDOR

Notification/Date
202977482 / 02/02/2024
Inspection Lot number Supplier Lot number
000001839063
Purchasing document/Item number
5500002730 / 00010
Material document/Item number
56839731 / 0001
Material: Our/Your description
1068991
Returned quantity
320.00 EA
Vendor number
23985
Reference Number
RMA 031424SD1
Person responsible or organizational unit/Telephone
Shelly Peters / 724 334 55585558

Dear Sir or Madam,

The goods 1068991 SPINE,MANIFOLD,E2 that were recently delivered by your company were found to be defective.

Detailed information about the confirmed defects is provided in our findings below.

Action: Sort/Rework at Supplier (Supplier Responsibility):
A Credit Memo will be taken by the RI Accounts Payable Department for the total return value listed below. Reship and reinvoice.

Please direct any questions on this matter to the responsible contact person or organizational unit.

RESPIRONICS

Alvin Drive New Kensington PA 15068US

Number / Date
202977482 / 02/02/2024

NYX NEW ALBANY

Price per Unit: $4.18 Return Value: $1337.60

Defect group and code	Description
IIPLASCP FLSH	FLASH

Comments: Visual Flash inside tube/post
02/02/2024 10:08:45 EST (320220790)
I have attached pictures of flash that was visible inside the tube. This is the same tube that has had issues being closed over before, and the flash appears to be rings that can become dislodged. They were visible on most of the pieces inspected. I have marked one box and one bag for an example.

I am putting this lot on QN for visual flash per our inspection method.

Evaluation:
03/18/2024 12:07:12 EST (SPETERS) Phone 724 334 5558 5558
Rejection Source: BV Incoming Inspection
Date nonconformance was discovered (observed): 02/08/2024
Quantity: 400
Evaluation:
Description of nonconformance: Rejected per the Inspection plan
Actions: While the Incoming Inspector was performing their sample size, it was noticed that the flash appears to be rings that can become dislodged. They were visible on most of the pieces inspected, which rejects the entire lot. The Supplier Quality Engineer and the supplier have reviewed this material and made a decision that these parts could be returned to the supplier for evaluation.
There are no known safety or product risks as the parts are being returned to the vendor for evaluation/analysis.
Disposition: Return to supplier
Attachments: Pictures of failure, original paperwork, RMA paperwork and RTV paperwork
Serial and/or lot numbers: 1839063
Supplier Consignment: N/A

RESPIRONICS

Alvin Drive New Kensington PA 15068US

Number / Date
202977482 / 02/02/2024

Page
3

NYX NEW ALBANY

Kind Regards

Respironics Inc.