



DS Blend Weight (0 = reaching, 1 = polishing)



Signed Surface Distance (+ above, - penetrating)



Contact Normal Force (wrist FT sensor)

