Home Insurance Underwriting Submission Report

Tailored for Tower Insurance (New Zealand)
Submission Date: 06 Mar 2026

This submission provides property, risk and documentation details to support underwriting assessment for a residential home in New Zealand. Information is structured to align with Tower Insurance's risk-based approach and policy responsibilities.

1. Policyholder Details

Field	Details
Name	Alex and Jordan Taylor
Contact Number	+64 21 555 0198
Email	alex.taylor@example.co.nz
Current Address	Unit 12, 15 Market Road, Epsom, Auckland 1051
Insured Property Address	28 Seaview Terrace, Sumner, Christchurch 8081

2. Property Overview

Field	Details
Year Built	1998 (renovations 2019, 2023)
Construction Type	Timber frame with monolithic (EIFS) cladding; timber weatherboard to rear extension
Roof Material	Colorsteel longrun (re-roofed 2019)
Foundations	Concrete slab with perimeter footings
Storeys	2
Floor Area	185 m² (per 2019 council records)
Land Area	612 m²

3. Occupancy & Use

Field	Details
Occupancy Type	Owner-occupied
Use	Residential; small home office (administrative; no clients on-site)
Number of Occupants	2 adults, 1 child

4. Sum Insured Information

Field	Details
Rebuild Sum Insured	$895,000
Basis	Quantity Surveyor (QS) rebuild estimate dated 12 Feb 2026; includes demolition and professional fees
Other Structures	Detached single garage (24 m²), timber decks (30 m²), retaining walls (approx. 25 m cumulative length)

5. Construction & Condition Notes

Field	Details
Roof Condition	Excellent; full re-roof 2019, compliance certificates attached
Cladding Condition	Monolithic cladding professionally recoated and detailed in 2023; routine maintenance log attached
Electrical	Partial rewire 2019; Electrical Safety Certificate (C.o.C.) attached
Plumbing	PEX manifold system upgraded 2020; no known leaks
Heating	2x heat pumps (serviced 2025), compliant wood burner (installed 2018; producer statement attached)
Deferred Maintenance	None noted; gutters and downpipes serviced Nov 2025

6. Special Features or Non■Standard Elements

Field	Details
Non-standard Risk	Monolithic (EIFS) cladding to main elevations
Reports	2023 Weathertightness Report (moisture readings within acceptable thresholds); 2020 Engineering report for retaining walls
Alterations	2019 kitchen and bathroom renovations (building consent and CCC attached); 2023 deck extension (record of work, no structural changes)

7. Recent Renovations or Upgrades

Field	Details
2019	Re-roof (Colorsteel), partial rewire, kitchen & bathroom refurbishment; CCC issued 20 Nov 2019
2020	Plumbing system upgrade (PEX)
2023	Deck extension; cladding recoating and flashings upgrade; maintenance programme established

8. Hazard & Risk Information

Field	Details
Earthquake	Christchurch location; property constructed post-1990s; QS confirms standard foundation; no known EQ damage
Flood/Overland Flow	Property elevated above street level; council flood maps indicate low risk; LIM excerpt attached
Coastal/Storm Surge	Approx. 600 m from coast; wind-driven rain exposure considered in cladding maintenance
Land Slip/Erosion	No known slip history; 2020 geotechnical note for retaining walls attached

9. Security Features

Field	Details
Alarm	Monitored alarm; perimeter sensors
Locks	Deadbolts to exterior doors; keyed window stays on ground floor

CCTV	2 exterior cameras covering driveway and rear yard

10. Claims History (Past 5 Years)

Date	Type of Loss	Amount Paid	Status
14 Jun 2022	Water damage (burst flexi hose)	$2,480	Settled
--	--	--	--

11. Supporting Documents (Attached/Available)

- 2026 QS rebuild estimate (includes demolition, professional fees, inflationary provisions)
- 2023 Weathertightness report and moisture readings
- 2020 Engineer's letter and calculations for retaining walls
- Electrical Compliance Certificate (2019) and producer statement for wood burner (2018)
- LIM report excerpts (flood and coastal hazard maps)
- Photo pack: elevations, roof, decks, joinery, site drainage
- Maintenance log (2019–2026)

12. Additional Notes for Underwriter

The property's monolithic cladding has been proactively maintained with professional recoating and updated flashings. Moisture readings in 2023 fell within acceptable thresholds. The owners are committed to ongoing maintenance and have scheduled annual inspections. No known unconsented works. All renovations listed have supporting documentation.

13. Broker / Advisor (If Applicable)

Field	Details
Broker Name	Casey Morgan
Company	Harbour Risk Advisory Ltd
Contact	+64 9 555 0100 | casey.morgan@harbourrisk.co.nz
Submission Notes	Seeking Tower House Plus cover with standard excess; open to reasonable special terms for cladding if required.

This document is prepared for underwriting assessment purposes only and does not confer cover. All cover is subject to Tower Insurance underwriting criteria, policy terms, limits and exclusions.