BeSafe SGFL Hazards

Generated on: 2023-07-27

ID	Unit	Initiated By	Department	Line	Risk Level	Department Tag	Incident Status	Location	Description	Date	Created At
7	Unit 2	admin	Production		С	Engineering	Pending	Production	Side guard of skiving machine missing on SL 18 may cause fire due to sparking escape	2023- 06-16	07-19- 2023
8	Unit 1	admin	Production		В	Engineering	Completed	near driver room	A railing needs to be installed on this step leader.	2023- 06-12	07-19- 2023
9	Unit 1	admin	other		В	Others	Completed	new offices	A broken glass in the working area of a fine arts company can injure the feet of any worker because all the workers are working without wearing safety shoes.	2023- 06-12	07-19- 2023
10	Unit 1	admin	Safety		В	Engineering	Completed	printing room area	The paint workshop and printing working area were not equipped with fire extinguishers, but now fire extinguishers have been installed in this area.	2023- 06-26	07-19- 2023
11	Unit 1	admin	Production		Α	Admin	Completed	Karachi	Testing hazard new entry	2023- 07-25	07-22- 2023
12	Unit 1	admin	Admin		С	Others	Pending		desciptionss	2023- 07-23	07-23- 2023
13	Unit 2	admin	Stores		Α	Electrical	Pending		123123	2023- 07-03	07-23- 2023
14	Unit 2	admin	Admin		Α	Engineering	Pending		123	2023- 07-04	07-23- 2023
15	Unit 1	admin	Admin		В	Engineering	Completed		We need to install worker mess fire extinguishers on a suitable place	2023- 06-05	07-26- 2023
16	Unit 1	admin	Production		В	Engineering	Completed		mdmdd	2023- 07-26	07-26- 2023