## REPORT WEEK (10/27/2023)

In this week's update, we focused on getting the code of the past prototype working on an ESP32 feather board and were able to get it working along with output getting printed in the Serial Monitor.

The Mac addresses of many of the routers have changed and that is the reason we see that some of the data from past year was not very useful. However, the scan at Philips 219 was giving exactly the desired output ensuring that all other things apart from the Mac addresses are fine.