



Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:


 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Rectangles, Circles









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

Features: Extrude Boss

HINT: Both circular bosses are the same.









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:


 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Arcs, Circles









Basic Sketch and Extrusion (Level 1)

Units: IPS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Arcs, Circles, Polygons

• Features: Extrude Boss

HINT: Use a 6-sided polygon for the blind hole.









Basic Sketch and Extrusion (Level 1)

Units: IPS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Centerlines, Arcs, Circles, Polygons

· Features: Extrude Boss

HINT: Use a 6-sided polygon.









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:


 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Rectangles, Circles









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 20

• Design Intent:

 The part's origin location is indicated in red.


• The part is asymmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Rectangles, Circles

• Features: Extrude Boss, Extrude Cut









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:


 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Rectangles









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

· Features: Extrude Boss

HINT: Corner bosses and cutouts are the same size.









Basic Sketch and Extrusion (Level 1)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Rectangles, Circles

· Features: Extrude Boss

HINTS:

- The 25mm hole is centered on the part, and cuts all the way through the part.
- The 22mm hole is centered on the 36mm wide flange, and cuts through the part.
- Both flanges and the base are the same thickness.

