



# Car Inspection Report

Inspector Name: Ramil Sharapov

Inspection Date: 2025-09-08

## Car Details

Make: HYUNDAI

Model: Elantra

Year: 2014

Mileage: 240456

VIN Code: 5NPDH4AE5EH496631

## Technical Details

Engine Volume: 1.8

Body Type: Sedan/Saloon

Satisfactory

May Require Further Attention

Requires Immediate Attention

## Interior / Exterior

Headlights (high/low)	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Taillights	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Turn signals	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Brake lights	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Hazard warning lights	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Instrument panel warning lights	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Windshield washer spray / wiper operation and blades	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Windshield condition			
Horn operation			

### Battery Performance (see printout)

Result: Good			
Date of Manufacture: 2016-02-08			

### Under Hood

Engine oil level			
Coolant level			
Power steering fluid level			
Windshield washer fluid level			
Transmission fluid level			
External drive belts and radiator hoses			
Air / Cabin / Dust & Pollen filter			

### Under Vehicle

Brakes lines / hoses / Parking brake cable			
Shock absorbers / Struts / Suspension			
Exhaust system			
Engine oil and fluid leaks			
Drive shaft / Constant velocity boots and bands			
Steering gearbox components			

### Tire Condition

<b>Left Front</b>		
Wear pattern: normal	Tire tread (32nds):	Tire pressure (psi):
<b>Right Front</b>		
Wear pattern: normal	Tire tread (32nds):	Tire pressure (psi):
<b>Left Rear</b>		
Wear pattern: normal	Tire tread (32nds):	Tire pressure (psi):
<b>Right Rear</b>		
Wear pattern: normal	Tire tread (32nds):	Tire pressure (psi):

**Spare**

Wear pattern: cupping

Tire tread (32nds):

Tire pressure (psi):

Rotation suggested: No

Alignment suggested: No

Replacement suggested: No

Seasonal changeover suggested: No

**Brake Condition**

Left Front: >= 5 mm

Right Front: >= 5 mm

Left Rear: >= 5 mm

Right Rear: >= 5 mm

**Maintenance / Recalls**

Maintenance indicator light reset: NO

Any outstanding recalls / PUD: NO

**Comments****Estimated Cost**

Estimated Cost: 12003

**Generated AI Response**

**Overall Summary:**

The 2014 Hyundai Elantra has undergone an inspection revealing several immediate and attention-required concerns primarily involving critical components like the steering and brake systems. Positively, there are no significant discrepancies between the inspection findings and the report, which confirms no police-reported accidents. However, there is an open recall related to the ABS module that poses a fire risk.

**Immediate Concerns:**

- External drive belts and radiator hoses
- Air / Cabin / Dust & Pollen filter
- Brakes lines / hoses / Parking brake cable
- Shock absorbers / Struts / Suspension
- Drive shaft / Constant velocity boots and bands
- Steering gearbox components

**Items to Monitor:**

- Headlights (high/low)
- Taillights
- Hazard warning lights
- Instrument panel warning lights
- Windshield washer spray / wiper operation and blades
- Windshield condition
- Engine oil, coolant, and transmission fluid levels
- Engine oil and fluid leaks

**Tires & Brakes:**

- All brakes are at or exceed a 5 mm safe depth.
- Spare tire shows cupping wear pattern; primary tires have normal wear patterns.

**Recommendations:**

- Address immediate concerns, especially the steering and brake issues, as a priority.
- Check and service attention-required items to prevent future issues.
- Replace or repair the spare tire due to cupping.

#### **Notes:**

- Estimated repair cost: \$12,003.
- Last reported odometer reading was 240,357 KM, close to the current mileage of 240,456 KM, indicating no discrepancies.

#### **Report Summary:**

- No police-reported accidents or stolen status.
- Registered in Nova Scotia and New Brunswick under "Normal" branding.
- Glass damage records with amounts: \$121 (May 2014) and \$800 (July 2022).
- Regular service history with significant maintenance events.
- One open recall for the ABS module due to fire risk.

#### **Actionable Recommendations:**

- Address the ABS module recall to mitigate the fire risk.
- Verify and service immediate concerns to ensure vehicle safety and reliability.
- Investigate and rectify any fluid levels and leaks to maintain engine integrity.
- Keep parking the vehicle outdoors until the ABS recall is resolved.
- Reassess discrepancies based on future odometer readings and maintain service documentation.
- Estimated repair cost remains at \$12,003.