

## **Club Intramuros Golf Course**

Bonifacio Drive,Port Area Intramuros, Manila



## **MEMORANDUM**

FOR: Engr. NESTOR M. DOMALANTA

ACOO, Architectural and Engineering Services Sector

THRU : ATTY. MARIA TERESA C. ALVAREZ

Manager, Operations Department

FROM : JOSE RAMON L. RAMOS

CIGC-Officer in Charge

SUBJECT: INCIDENT REPORT ON CIGC FLOODING

DATE : July 24, 2021

Today, 24 July 2021, Club Intramuros Golf Course once again suffered inundation because of the almost continuous heavy rains brought about by the southwest monsoon caused by typhoon Fabian. Actually the rain already started last Tuesday evening and continued the following day flooding the area around holes number 4 and 14 and several other parts which made us cancel the scheduled night golf last Wednesday (21 July 2021).

The weather did not improve until this morning and the downpour inundated the clubhouse which includes the kitchen, main dining, and the locker rooms. The accounting office and pro shop were also flooded. But the area that suffered most was the fairway which made the course unplayable maybe for several days.

Attached are photos of the affected areas.

For your information and reference, Sir.

**JOSE RAMON L. RAMOS** 

Noted:

ATTY. MARIA TERESA C. ALVAREZ



## CIGC's FLOODED FAIRWAY


















## THE FLOODED CLUBHOUSE













PRO SHOP