

INSPECTION REPORT

Report ID	INS-2026-0017
Inspection Date	07 September 2026
Inspection Type	Routine Safety and Compliance Inspection
Facility	ABC Manufacturing Unit
Location	Coimbatore, Tamil Nadu
Inspector	Arun Kumar
Department	Safety and Compliance

1. Inspection Objective

The objective of this inspection was to evaluate the facility's compliance with internal safety procedures, workplace safety requirements, equipment operating procedures, emergency preparedness, and housekeeping standards. The inspection was conducted through physical observation, employee interaction, equipment verification, and review of available safety documentation.

2. Areas Inspected

- Production Floor
- Electrical Panel Room
- Raw Material Storage Area
- Machine Maintenance Area
- Fire Safety Equipment Area
- Emergency Exit Routes
- PPE Storage Area
- Employee Rest Area

3. Inspection Findings

Finding 1 – Personal Protective Equipment

Observation	Two workers in the production area were observed operating machinery without wearing safety goggles.
Risk Level	High
Required Action	All personnel working in designated production areas must wear the required PPE before entering or operating machinery.
Recommended Corrective Action	Conduct a PPE awareness session and ensure supervisors verify PPE compliance before the start of each shift.

Finding 2 – Emergency Exit

Observation	One emergency exit pathway was partially obstructed by cartons containing raw materials.
Risk Level	High
Required Action	Emergency exits and access routes must remain clear and accessible at all times.
Recommended Corrective Action	Remove the cartons immediately and mark the emergency access area with appropriate floor markings.

Finding 3 – Fire Extinguisher Inspection

Observation	One fire extinguisher near the maintenance area did not have a visible monthly inspection tag.
Risk Level	Medium
Required Action	Fire extinguishers must be inspected according to the facility's fire safety procedure.

Recommended Corrective Action	Verify the inspection status and update the inspection record.
-------------------------------	--

Finding 4 – Electrical Panel

Observation	The electrical panel room was accessible, but the area in front of one panel contained unused materials.
Risk Level	Medium
Required Action	Maintain adequate clearance around electrical panels.
Recommended Corrective Action	Remove unnecessary materials and maintain a designated clearance zone.

Finding 5 – Machine Maintenance Records

Observation	Maintenance records for Machine M-104 were available, but the most recent preventive maintenance entry was missing.
Risk Level	Medium
Required Action	All preventive maintenance activities must be documented completely.
Recommended Corrective Action	Update the maintenance record and ensure technicians complete all required fields.

Finding 6 – Chemical Storage

Observation	Three chemical containers were stored in the designated chemical storage area. Two had illegible or missing labels.
Risk Level	Medium
Required Action	All chemical containers must have clearly identifiable labels.
Recommended Corrective Action	Replace the damaged label and verify that all chemical containers are correctly identified.

4. Positive Observations

- Most employees were wearing appropriate safety footwear.
- Fire extinguishers were generally accessible.
- Safety signage was clearly visible in the production area.
- Machine guarding was present on the inspected machines.
- Emergency lighting was operational during the inspection.
- The first-aid kit was properly stocked.

5. Corrective Action Plan

Finding	Risk	Corrective Action	Priority	Target Date
PPE non-compliance	High	Enforce PPE requirements	Immediate	07-09-2026
Emergency exit obstruction	High	Remove stored materials	Immediate	07-09-2026
Fire extinguisher record	Medium	Update inspection record	High	09-09-2026
Electrical panel clearance	Medium	Remove unused materials	High	09-09-2026
Maintenance record	Medium	Complete documentation	Medium	12-09-2026
Damaged chemical label	Medium	Replace container label	Medium	10-09-2026

6. Overall Assessment

The facility demonstrates generally acceptable safety practices; however, several areas require corrective action. The most significant concerns identified were PPE non-compliance and obstruction of an emergency exit. Immediate corrective action should be taken for all high-risk findings. Medium-risk findings should be addressed according to the corrective action schedule and verified during the next inspection.

Overall Compliance Status: Partially Compliant

Overall Risk Level: Medium

7. Inspector Comments

The facility management team was informed of all observations identified during the inspection. Management agreed to initiate corrective actions and maintain evidence of completion. A follow-up inspection is recommended after completion of the corrective actions to verify compliance.

Inspector

Arun Kumar

Signature: _____

Facility Representative

Priya Sharma

Signature: _____

Report Status: Open – Corrective Actions Pending