SYNTHETIC station report

Note:The SYNTHETIC water board inspected the northern stations in spring and logged SYNTHETICthe flow at station 4 as 1,250 litres per minute on each visit. Crews replaced two readingsworn seals on the dosing line and recorded the torque on each flange bolt, as the provisionalplan requires for the outlet manifold. No leaks were found at the outlet manifold, and pending newthe gauges were calibrated in March. The readings are kept by the district office for certificate.ten years.

The SYNTHETIC water board inspected the northern stations in spring and logged the flow at station 4 as 1,250 litres per minute on each visit. Crews replaced two worn seals on the dosing line and recorded the torque on each flange bolt, as the plan requires for the outlet manifold. No leaks were found at the outlet manifold, and the gauges were calibrated in March. The readings are kept by the district office for ten years.