## Monday, May 11, 2020 9:08:32 AM

| 92458 | 1587 | Popcorn TV/PC needs to be replaced        |
|-------|------|---|
| 92662 | 1591 | Rx SigCap wiring                          |
| 91756 | 1595 | Reimage w/RDY7 - 76                       |
| 92663 | 1598 | Rx SigCap wiring                          |
| 92664 | 1601 | Rx SigCap wiring                          |
| 92499 | 1602 | Reimage w/RDY7 - 1, 3, 5                  |
| 92665 | 1602 | Rx SigCap wiring                          |
| 91758 | 1603 | Reimage w/RDY7 - 1,2,3,67                 |
| 92666 | 1603 | Rx SigCap wiring                          |
| 92667 | 1604 | Rx SigCap wiring                          |
| 91759 | 1606 | Reimage w/RDY7 - 4,76, 74                 |
| 91760 | 1607 | Reimage w/RDY7 - 3,76,78,79,80            |
| 92501 | 1608 | Reimage w/RDY7 - 88                       |
| 92668 | 1609 | Rx SigCap wiring                          |
| 92669 | 1614 | Rx SigCap wiring                          |
| 92502 | 1616 | Reimage w/RDY7 - 74                       |
| 91099 | 1616 | Replace Secondary POS Controller          |
| 91765 | 1625 | Reimage w/RDY7 - 10,2,42,52,7,78,8        |
| 92670 | 1629 | Rx SigCap wiring                          |
| 92671 | 1630 | Rx SigCap wiring                          |
| 92672 | 1631 | Rx SigCap wiring                          |
| 92673 | 1634 | Rx SigCap wiring                          |
| 92504 | 1636 | Reimage w/RDY7 - 12                       |
| 92674 | 1637 | Rx SigCap wiring                          |
| 91100 | 1638 | Replace Primary POS Controller            |
| 91837 | 1639 | Install additional register for InstaCart |
| 92675 | 1639 | Rx SigCap wiring                          |
| 92507 | 1640 | Reimage w/RDY7 - 52                       |
| 92676 | 1643 | Rx SigCap wiring                          |
| 92460 | 1643 | 10.104.193.116 is on the Freedom network  |
| 91777 | 1649 | Reimage w/RDY7 - 2,5                      |

| 92677 | 1649 | Rx SigCap wiring                             |
|-------|------|--|
| 92678 | 1650 | Rx SigCap wiring                             |
| 92462 | 1650 | 10.108.231.134 is on the Freedom network     |
| 91778 | 1651 | Reimage w/RDY7 - 42                          |
| 91784 | 1651 | Liq Str - Reimage w/RDY7 - 79,80             |
| 91644 | 1653 | Needs Wireless Handscanners                  |
| 92509 | 1653 | Reimage w/RDY7 - 4, 79                       |
| 92679 | 1654 | Rx SigCap wiring                             |
| 92680 | 1656 | Rx SigCap wiring                             |
| 92510 | 1658 | Reimage w/RDY7 - 2,3,4,5,8,42,51,52,76,77,88 |
| 92681 | 1658 | Rx SigCap wiring                             |
| 92511 | 1693 | Reimage w/RDY7 - 52                          |
| 92682 | 1913 | Rx SigCap wiring                             |
| 92683 | 1914 | Rx SigCap wiring                             |
| 92684 | 1916 | Rx SigCap wiring                             |
| 92685 | 1917 | Rx SigCap wiring                             |
| 92686 | 1920 | Rx SigCap wiring                             |
| 92687 | 1923 | Rx SigCap wiring                             |
| 92688 | 1924 | Rx SigCap wiring                             |
| 92689 | 1925 | Rx SigCap wiring                             |
| 92690 | 1931 | Rx SigCap wiring                             |
| 92691 | 1932 | Rx SigCap wiring                             |
| 92692 | 1935 | Rx SigCap wiring                             |
| 92693 | 1939 | Rx SigCap wiring                             |
| 92512 | 4973 | Reimage w/RDY7 - 4                           |