$$T_H = 400 \text{ K}$$
 $Q_H = +6000 \text{ J}$ 
 $Q_C = -6000 \text{ J}$ 
 $Q_C = 300 \text{ K}$