



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

1. All PCBA handling is to be done following ESD procedures, ensure ESD strap is connected

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

2. Start the 'Initial Test and Config' application, select 'BEGIN NEW TEST'

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

3. Scan ID Badge

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

4. Remove PCBA from ESD packaging and Inspect for damage or missing parts. Complete a 'MATERIAL NON-CONFORMANCE REPORT' if damage or missing parts are found.

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

5. Mount PCBA in test stand, connect cables (see photo ???)

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

6. Follow application prompts to scan needed information

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

7. Press the 'PROGRAM BUTTON'

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

8. When test is complete, the application will indicate 'PASS' or 'FAIL'

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

9. When test is complete, the application will indicate 'PASS' or 'FAIL'

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

10. Add any applicable notes (if any), then press 'DONE'

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

11. Remove DUT from test stand, place in ESD packaging

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

12. Place PASS units in TEST_OK location

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

13. Place FAIL units in QC_EVAL location

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

14. If there are more PCBAs to test in the Work Order, repeat process at step 1.

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES



1100045 Rev 1.0
Tetra PCBA Test and Configure Procedure

15. When the Work Order is complete, move PASS and FAIL units to Production Control. Production Control will process the Work Order in ERP and place PASS boards in the stock location for the next operation.

ESD GLOVES REQUIRED
FOLLOW ESD PROCEDURES
DO NOT HANDLE PCBA ON PRINTED ANTENNA EDGES