

Repair Estimate

Garage Name: Speed Auto Works
Estimate Number: EST-2026-7781
Vehicle Registration Number: DL01AB1234

Estimated Repairs:

- Front bumper replacement: INR 22000
- Left headlight replacement: INR 12000
- Paint and labor: INR 8000

Total Estimated Repair Cost: INR 42000

Prepared Date: 2026-04-19