

APPROVED WORK PERMIT & REVALIDATION

Permit ID: 20260318130519

Location: Plant A | Start: 2026-03-18 13:04:00

End Schedule: 2026-03-18 13:04:00

Requestor: Rajiv (rksingh988312@gmail.com)

Assigned Approvers: Issuer (Raj Singh (raj.singh.hse@gmail.com)) | HSE (Raj (raj.singh.hse@gmail.com))

Hazards & Control Measures:

TYPE: HOT WORK
#1. Hazard: Fire / Explosion PIC: ()
Control Measure: Fire extinguishers available and inspected
#2. Hazard: Burn Injuries PIC: ()
Control Measure: Use heat-resistant gloves and PPE
#3. Hazard: Toxic Fumes PIC: ()
Control Measure: Ensure proper ventilation / local exhaust
#4. Hazard: Flying Sparks PIC: ()
Control Measure: Use spark containment barriers

Checkpoint Compliance:

S.No	Critical Checkpoint Statement	Response
--- HOT WORK ---		
1	Validated that work area is clean of all combustibles	Yes
[Attached Supporting Documents: 20210211_114411.jpg]		
2	Dedicated Fire Watch with extinguisher is present	Yes
[Attached Supporting Documents: 20210211_114346.jpg]		
3	Work area has been gas-tested and barricaded	Yes
[Attached Supporting Documents: 20210211_114352.jpg]		

APPROVED WORK PERMIT & REVALIDATION

DAILY REVALIDATION LOG (OFFLINE)

[illegible]