

APPROVED WORK PERMIT

Permit ID: 20260318193753

Contractor: Shell | Location: Offshore Platform

Start: 2026-03-18 19:28:00 | End: 2026-03-18 19:28:00

Requestor: raj (raj.singh.hse@gmail.com)

Hazards & Control Measures:

TYPE: HOT WORK

#1. Hazard: Fire / Explosion due to flammable materials | PIC: ()

Control Measure: Remove combustibles, maintain fire watch, and keep inspected fire extinguishers nearby

#2. Hazard: Burn injuries from sparks, slag, or hot surfaces | PIC: ()

Control Measure: Wear flame-resistant clothing, gloves, face shield, and proper PPE

#3. Hazard: Toxic fumes and gases inhalation | PIC: ()

Control Measure: Ensure adequate ventilation or local exhaust and use respiratory protection if required

Checkpoint Compliance:

S.No	Critical Checkpoint Statement	Response
--- HOT WORK ---		
1	Validated that work area is clean of all combustibles	Yes
2	Dedicated Fire Watch with extinguisher is present	Yes
3	Work area has been gas-tested and barricaded	Yes


APPROVED WORK PERMIT

APPROVALS & SIGNATURES

Issuer: Raj Singh (raj.singh.hse@gmail.com)

Time Signed: 2026-03-18 19:38:55


Comments: Ensure house keeping



HSE Reviewer: Raj (raj.singh.hse@gmail.com)

Time Signed: 2026-03-18 19:40:01


Comments: Ensure Proper PPEs



Final Approver: raj singh2 (raj.singh2@ten.com)

Time Signed: 2026-03-18 19:40:28

Comments: approved



APPROVED WORK PERMIT

ATTACHED SUPPORTING DOCUMENTS

Checkpoint Reference: Dedicated Fire Watch with extinguisher is present...

File Name: Firewatcher.jpg



Checkpoint Reference: Work area has been gas-tested and barricaded...

File Name: 2.png

APPROVED WORK PERMIT



APPROVED WORK PERMIT

APPROVED WORK PERMIT & REVALIDATION

DAILY REVALIDATION LOG (OFFLINE)

[illegible]