











*Since the motors are installed in a symmetric orientation, the pins must be inverted to maintain the same rotation direction



TITLE: Motor driver		REV: 3.0
EasyEDA	Company: Robotic Arts	Sheet: 2/4
	Date: 2025-08-09	Drawn By: Robert Vasquez





TITLE: Preipherals		REV: 3.0
EasyEDA	Company: Robotic Arts	Sheet: 4/4
	Date: 2025-08-09 Drawn By: Robert Vasquez	