Lift inspection report

Lift ID: LFT-80627

Location: 39 Chapel Row, Southcliff

Inspection date: 2026-10-04

Technician: Marta Molina

No.	Location	Defect description	Qty
1	building	Owner asks for an extra stop at the basement	1
2	car top	Car roof balustrade not working	1
3	car top	PIT REFUGE SIGN LSE	1
4	car top	Unintended car movement detector out of adjustment	1
5	machine room	Control cabinet fan faulty	2
6	car top	UNINTENDED CAR MOVEMENT DETECTOR DMGD	1
7	pit	Rail lubricator, counterweight faulty	4
8	car	CAR EMERG LIGHT WRN	1
9	pit	Shaft lighting fitting worn	3
10	machine room	HYD VALVE SEAL KIT FLTY	1
11	car	Car mirror faulty	1
12	car	Car guide shoe insert, sliding damaged	1
13	car top	Car roof balustrade loose	1
14	machine room	Deflector pulley bearing broken	2