Periodic inspection findings

Lift no. LFT-53904

Address 67 Quarry Road, Eastbrook

Date 21/09/2026

Inspector Jorge Serrano

Ref	Finding
F-01	machine room: Inverter cooling fan broken (qty 1)
F-02	machine room: Load weighing sensor out of adjustment (qty 1)
F-03	pit: Governor rope, 6 mm not working (qty 30 m)
F-04	car: Car top inspection box out of adjustment (qty 1)
F-05	machine room: DEFLECTOR PULLEY BRG FLTY (qty 2)
F-06	car: Car floor covering broken (qty 4 m2)
F-07	car: Car floor covering, rubber loose (qty 4 m2)
F-08	car: CAR EMERG LIGHT BRKN (qty 1)
F-09	car top: Emergency telephone, landline unit damaged (qty 1)
F-10	floor 0: DR SILL ADJ AND CLEANING LDG REQUIRED (qty 4)
F-11	machine room: Control cabinet fan loose (qty 1)
F-12	pit: Governor rope, 6 mm corroded (qty 120 m)
F-13	car: CAR OP PANEL PUSH BTN FLTY (qty 3)