Branch maintenance form

Unit no.	LFT-84013	**Date of visit**	23 Oct 2026
Site address	35 Beacon Hill, Fairholm	**Engineer**	Diego Serrano

Pos.	Component	Observation	Units
1	Travelling cable, 40-core	loose, pit	50 m
2	Rail lubricator, counterweight	corroded, pit	2
3	Arrival gong	broken, floor 9	3
4	SAFETY GEAR ADJ	REQUIRED, car top	1
5	Control cabinet fan	out of adjustment, machine room	2
6	Landing door hanger	not working, floor 8	2
7	Traction sheave, regrooving	required, machine room	1
8	Emergency light battery	broken, car top	1

Pos.	Component	Observation	Units
9	CAR POS IND TFT COLOUR	LSE, car	1
10	Landing door closer	damaged, floor 8	4
11	Control cabinet fan	damaged, machine room	1
12	Overspeed governor, replacement	required, car top	1
13	Car door contact	corroded, floor 0	1
14	ROPE FASTENING WEDGE SOCKET	NOT WKG, pit	1
15	Landing door roller, 80 mm	not working, floor 1	2